

Software Release - 16 March 2023

New Features

- New users' and cards' status icon display
- Compatible with the KPROG enrolment device
- Batch Loading available through the web page
- User Custom Reports and Report Templates *
- Global Settings: Save Event Option *
- Global Settings: User Custom Fields Option *
- Optimised with Cache Read/Write * §
- Supports Factory default/Reboot master command * §
- Shows Expanders related events in System Overview
- New Fast Sync module feature * §
- New factory reset command that also keeps the module as a master * § (minimises the number of reboots during restore of PC database)
- Software: "Last Access Event Date" feature. This will add a background colour to users who have not had an access event for more than 6 months. 6 months and longer without an event the background colour will be amber, after 12 months the colour will change to red.
- Software System Overview improvements:
 - Shows interrogation marks for all modules affected by a conflicted module warning
 - Shows reader name after the module name (easier for the installer to find issues).
 - Modification to the search text and F3 will select the next node from the find results.
- Supports K5 reader

Bug Fixes

- Fixed show status of elevator floor event on global unlock.
- Fixed account creation/update issue where the DAC service was unable to deploy database.
- Fixed getting the disk file size of the account database was affecting the DAC service.
- Display of error message on account creation or update failed (Windows 11 issue).
- Fixed User Counter loading all user counters when nothing is programmed.
- Fixed memory exception in License Properties.
- Fixed invalid license status in License Properties.
- Fixed double loading of partially buffered events.
- Fixed unknown module name for module reconnected, missing events.
- Fixed re-synchronisation on a mismatch database process.
- User can now delete outputs from readers.
- Fixed synchronisation issues.
- Fixed "User Location" button that was not available when a module was offline.
- Fixed Global Settings flashing button.
- Fixed out of memory exception caused by User Grid updating processes.
- Fixed Card Number and Access Level name that were missing in event description.
- Fixed Holiday name missing in event description.
- Added missing HID-48 Bit card format in the software.

* Works with A22K firmware version 3.02.084

§ Works with A22 firmware version 5.00.544